

# NATIONAL TRANSPORTATION SAFETY BOARD

Office of Research and Engineering  
Materials Laboratory Division  
Washington, D.C. 20594



July 29, 2003

MATERIALS LABORATORY FACTUAL REPORT

Report No. 03-082

## A. ACCIDENT

Place : Tillamook Inlet, Garibaldi, Oregon  
Date : June 14, 2003  
Vehicle : SPV Taki-Tooo  
NTSB No. : DCA03MM035  
Investigator : Rob Jones, MS-10

## B. COMPONENTS EXAMINED

Propeller


## C. DETAILS OF THE EXAMINATION

An overall view of the aft side of the propeller from the Taki-Tooo is shown in figure 1. The propeller was submitted to document any damage. For ease of reference, the propeller blades have been numbered "1" through "4" as shown in figure 1.

The tip of each blade was curled in the forward direction. The total angle of the curl and the area over which the curl occurred increased in the counter clockwise direction (aft looking forward) from blade "1" through blade "4", with damage over about  $\frac{3}{4}$  inch on blade "1" and over about 1.5 inches on blade "4" (see figure 2). The aft side of the blades did not contain any type of scoring marks or scraping damage associated with the curls. The curl damage was consistent with contact of the propeller with a soft bottom while under power.


Additional damage was also noted on blade "1". Two areas of local deformation (approximately dime-sized) were noted on this blade, one approximately midway along the leading edge, and one on the trailing edge side of the curl. Forces acting on the forward side of the blade created these deformation areas, and the resulting deformation was in the aft direction. No evidence of impact from hard material was noted in these areas. The outer one third to one half of blade "1" was also bent in the aft direction, resulting in the tip being approximately 0.75 inch further aft than the tips of the other blades.

James F. Wildey II  
Supervisory Metallurgist



ImageNo:307A0255, Project No:A00542

Figure 1. Overall view of the aft side of the propeller, with the blades labeled "1" through "4".



ImageNo: 307A0593, Project No:A00542

Figure 2. View of the curl damage on blade "4".